## COUNCIL AGENDA ITEM # \_\_\_\_ FOR TUESDAY, MAY 10, 2005

#### **BUILDING PERMITS AND INSPECTIONS**

### MEMORANDUM April 22, 2005

TO: The Honorable Mayor and City Council

THROUGH: R. Alan Shubert, P. E. - Building Permits and Inspections Director

FROM: Tom Maguire, Housing Compliance Supervisor

SUBJECT: 131 Linden Street (Rep. District #3)

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated January 25, 2004. The building was found to be in an advanced state of disrepair. The building has been used as a harborage by unwanted persons.
- 2) A certified condemnation letter was mailed to Maria Lourdes and Carlos J. Corral, 131 Linden Street, El Paso, Texas 79905.
- 3) Certified notices of the public hearing scheduled for May 10, 2005 were mailed to the owners and all interested parties on April 26, 2005.
- 4) There has been no response from the owner.

### The Department recommends that it be found:

- 1) That the accessory building be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the building is not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structure's certificate of occupancy be revoked; and
- 4) Since no plans or documents have been submitted to indicate otherwise, the structure cannot be repaired; and
- 5) That the accessory building be demolished within 30 days; and
- 6) That the premises be cleaned of all weeds, trash, and debris within 30 days.

# CITY OF EL PASO, TEXAS AGENDA ITEM DEPARTMENT HEAD'S SUMMARY FORM

| DEPARTMENT:   | BUILDING PERMITS AND INSPECTIONS   |          |
|---|--|----------|
| AGENDA DATE:  | May 10, 2005   |          |
| CONTACT PERSON                                      | V/PHONE: TOM MAGUIRE 541-4800  | _        |
| DISTRICT(S) AFFEC                                   | CTED: <u>3</u>   |          |
| SUBJECT: APPROVE a Manager to d amount if app       | resolution / ordinance / lease to do what? OR AUTHORIZE the City lo what? Be descriptive of what we want Council to approve. Include \$ licable.   |          |
| APPROVE A USE OR HAB WELFARE.                       | RESOLUTION TO DECLARE THE PROPERTY AT 131 LINDEN STREET UNFIT<br>BITATION AND A HAZARD TO THE PUBLIC HEALTH, SAFETY AND  | 'FOR     |
| Discussion of t<br>complete descr<br>tabulation, or | ND / DISCUSSION: the what, why, where, when, and how to enable Council to have reasonably cription of the contemplated action. This should include attachment of bid ordinance or resolution if appropriate. What are the benefits to the City of What are the citizen concerns?   | _        |
| APPROVE, D  | ISAPPROVE OR POSTPONE DEPARTMENT RECOMMENDATIONS.  |          |
|   | NCIL ACTION: cil previously considered this item or a closely related one?   |          |
|   |  |          |
| How will this i                                     | ND SOURCE OF FUNDING: item be funded? Has the item been budgeted? If so, identify funding source mbers and description of account. Does it require a budget transfer?  |          |
| COST OF AC  | TION TO BE BILLED TO OWNER IF COUNCIL ORDER NOT COMPLIED WITH  | I, LIEN  |
| PLACED ON 1   | PROPERTY, IF NECESSARY.  |          |
|   | MMISSION ACTION: riate comments or N/A   |          |
| N/A   |  | _        |
| ****  | **************************************   |          |
| <b>LEGAL:</b> (if required)                         |  |          |
| DEPARTMENT HEA                                      |  |          |
|   | (Example: if RCA is initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing, client department should significant to the initiated by Purchasing significant significant to the initiated by Purchasing significant s | gn also) |
| APPROVED FOR A                                      | AGENDA:  |          |
| CITY MANAGER:                                       | DATE:  |          |

COPY

JOE WARDY MAYOR

JOYCE WILSON CITY MANAGER

R. ALAN SHUBERT, P.E. DIRECTOR



CITY COUNCIL

SUSAN AUSTIN DISTRICT NO. 1

ROBERT A. CUSHING, JR. DISTRICT NO. 2

JOSE ALEXANDRO LOZANO DISTRICT NO. 3

> JOHN F. COOK DISTRICT NO. 4

PAUL J. ESCOBAR DISTRICT NO. 6

## **BUILDING PERMITS & INSPECTIONS DEPARTMENT**

VIVIAN ROJAS DISTRICT NO. 7

HOUSING COMPLIANCE January 21, 2005 ANTHONY W. COBOS DISTRICT NO. 8

Citicorp Mortgage, Inc. C/O Maria L. & Carlos J. Corral 131 Linden St. El Paso, Texas 79905-3811

Re: 131 Linden St.

Lots: 13 & 14 & N 20 Ft. of 12

Blk: 1, Tobins Second

Zoned: R-5 COD05-00820

Certified Mail Receipt # 7004 1160 0007 2325 9917

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.52.030 - Unsafe Structures - Owner Not To Allow Condition To Continue, which states:

It is unlawful for the owner of any building or structure, or part thereof, which has become unsafe and dangerous so as to endanger persons or property, or so as to be a fire hazard by reason of defective construction, overloaded floors, lack of guards against fire, defective condition of the foundations, walls, or parts thereof, or deterioration caused by fire or otherwise, or for any reason, to allow or permit same to remain upon any real estate within the City.

The El Paso Municipal Code Chapter 18.52.040 - unsafe structures - Remedial action by owner or City defines unsafe structure as a structure or part thereof that is:

#### 131 Linden Street

- a. Dilapidated, substandard, or unfit for human habitation and a hazard to the public health, safety, and welfare; or
- Regardless of its structural condition, unoccupied by its owners, lessees or other invitees and is unsecured from unauthorized entry to the extent that it could be entered or used by vagrants or other uninvited persons as a place of harborage or could be entered or used by children; or
- c. Boarded up, fenced, or otherwise secured in any manner in if:
- i. The building constitutes a danger to the public even though secured entry, or
- ii. The means used to secure the building are inadequate to prevent unauthorized entry or use of the building in the manner described by subsection.

The structure located at 131 Linden Street has the following violations:

- a. The foundation has not been maintained in a safe manner.
- b. The floors have not been maintained in a safe manner.
- c. The walls have not been maintained in a safe manner free of holes and cracks.
- d. The roof structure has not been maintained free of defects that may cause leaks.
- e. The means of egress is/are inadequate and do not meet minimum code requirements.
- f. The plumbing system is inadequate and does not meet minimum code requirements.
- g. The electrical system is inadequate and does not meet minimum code requirements.
- h. The HVAC system is inadequate and does not meet minimum code requirements.

#### 131 Linden Street

- i. The premises are full of weeds, trash, and debris.
- j. This case is being submitted to the City Attorney's office for unsafe structures proceedings. The City Council will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Sec. 18.52.040 of the El Paso Municipal Code.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Housing Compliance Office of the Building Permits and Inspections, 5<sup>th</sup> floor, City Hall, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 54I-4800.

FOR THE DIRECTOR FOR BUILDING PERMITS AND INSPECTIONS:

Leo CassoLopez
Building Inspector

LC/rl

|  | d 1855   |
|--|--|
| SENDER: COMPLETE THIS SECTION  | COMPLETE THIS SECTION ON DELIVERY  |
| <ul> <li>Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.</li> <li>Print your name and address on the reverse so that we can return the card to you.</li> <li>Attach this card to the back of the mailpiece, or on the front if space permits.</li> </ul>   | A. Signature  A. Agent  Addressee  B. Received by ( Printed Name)  C. Date of Delivery  C. Same of Delivery  C. Same of Delivery |
| Article Addressed to: /  | D. Is delivery address different from item 1?  Yes   |
| " Alliote Addressed to.  | If YES, enter delivery address below: ☐ No   |
| Citicorp Mortgage, Inc. C/O Maria L. & Carlos J. Corral 131 Linden Street El Paso, Texas 79905-3811 Re: 131 Linden Street  | 3. Service Type  ② Periiffed Mail  |
| en e   | ☐ Registered ☐ Return Receipt for Merchandise ☐ Insured Mail ☐ C.O.D.  |
| 2k #5  | 4. Restricted Delivery? (Extra Fee) ☐ Yes  |
| 2. Article Number. (Transfer from service label) 7004 11   |  |
| PS Form 3811, February 2004 Domestic Retu  |  |
| L Taranta de la constanta de l | En BECEPT  Insurance Goverage Provided)  Our website at www.usps.com  2 1 2005  Postmark Here  Inc.                              |
| 7 131 Linden Street  |  |
| El Paso, Texas 7990  | 5-3811   |
| Re: 131 Linden Stre  |  |
| PS Form 3800, June 2002  | Sec Reverse for Institutions   |

### NOTICE OF PUBLIC HEARING

#### To All Interested Parties:

You are hereby notified that at 9:00 a.m. on the 10<sup>Th</sup> day of May, 2005 in the Council Chambers of City Hall, #2 Civic Center Plaza, El Paso, Texas, the City Council of El Paso will hold a public hearing on the question of whether the Building located on the property at 131 Linden Street Apt. B, in El Paso, Texas, which property is more particularly described as:

Lots: 13 and 14 and the North 20 feet of Lot 12, Block 1, Tobins Second Addition, an Addition to the City of El Paso, El Paso County, Texas, according to the map thereof on File in Book 16, Page 58, Plat Records of El Paso County, Texas

is unsafe and dangerous.

According to the real property records of the County of El Paso, Texas, Maria Lourdes and Carlos J. Corral, 131 Linden Street, El Paso, Texas 79905, are listed as the Owners of the real property described herein.

The Owners of said property are hereby ordered to appear before City Council and any mortgagees, lien holders, and other persons having an interest in said property are entitled to appear before City Council at said date, hour, and place to show cause why said Building should not be declared a nuisance and ordered to be abated; and

The Owners lien holders, mortgagees, or any other person having an interest in the property are hereby required to submit at the hearing proof of the scope of any work that may be required to bring the building into compliance with Titles 17 and 18 of the code as mandated by Section 18.52.040 of the Municipal Code, and to specify the time it will take to reasonably perform the work.

At the hearing, the owners, lien holders, mortgagees, or any other person having an interest in the property must present to City Council any evidence showing that the structure or part thereof is safe.

All documents such as building plans, specifications, drawings, reports from design professionals and any other required documents must be presented to City Council at this hearing.

The time periods, which govern the completion of work ordered by Council, are outlined in Subsection 18.52.040 (3) pursuant to State law.

If the Owners fail, neglect or refuse to comply with the order of City Council the City may pursue one, or more of the following actions:

- the city will perform any and all work needed to bring the property into compliance with this order, at its own expense, but for and on account of the Owners of said property, the cost of which shall be assessed as a lien against the property and;
- II) assess a civil penalty against the property Owners for failure to repair, remove or demolish said Building in an amount not to exceed \$1000.00 a day for each violation, or \$10 a day if the Owners show that the property is the Owner's lawful homestead and;
- III) the Owners may be confined in jail as permitted by state law and;
- IV) appoint a receiver as permitted by state law.

Any civil penalty or assessment imposed will accrue interest at a rate of ten (10) percent a year from the date of the assessment until paid in full; and

That the City Clerk is ordered to provide notice of this hearing to the record Owners and all other persons having an interest in the property as provided by law.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Housing Compliance Office of the Building Permits and Inspections, 5<sup>th</sup> floor, City Hall, no later than the 20<sup>th</sup> day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Adopted this 19<sup>th</sup> day of April, 2005.

| APPROVED AS TO FORM:                     | APPROVED AS TO CONTENT:                   |  |
|--|---|--|
|  |   |  |
| Lisa A. Hayes<br>Assistant City Attorney | Tom Maguire Housing Compliance Supervisor |  |

| I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice dated April 19 <sup>th</sup> , 2005 regarding the property located at 131 Linden Street Apt. B, was filed with the County Clerk's Office, the official public records of real property for El Paso County. |
|---|
| Richarda Duffy Momsen   |
| Executed this day of, 2005 on behalf of the City of El Paso, Texas, by Richarda Duffy Momsen in her capacity as City Clerk.   |
| STATE OF TEXAS COUNTY OF EL PASO  |
| Subscribed and sworn to before me, this day of, 2005.   |
| Notary Public   |

| I, RICHARDA DUFFY MOMSEN, City Clerk of the correct copy of the foregoing Notice dated April 131 Linden Street Apt. B, was PUBLISHED in the of, 2005.  | 19 <sup>th</sup> , 2005 regarding the property located at                                |  |
|--|--|--|
|  |  |  |
|  | Richarda Duffy Momsen  |  |
| I certify that a true and correct copy of the foregon property at 131 Linden Street Apt. B, was (MAILE REQUESTED) to:  | ing Notice dated April 19 <sup>th</sup> , 2005 regarding the ED CERTIFIED-RETURN RECEIPT |  |
| Maria Lourdes and Carlos J. Corral<br>131 Linden Street<br>El Paso, Texas 79905  |  |  |
|  | Date:  |  |
|  | Time:  |  |
|  | Inspector  |  |
| I certify that a true and correct copy of the forego<br>property at 131 Linden Street Apt. B, was (MAILE<br>REQUESTED) to:   |  |  |
| Maria Enriquez 59 N. Boone Street  |  |  |
| El Paso, Texas 79905   | Date:  |  |
|  | Time:  |  |
|  |  |  |
|  | Inspector  |  |
| I certify that a true and correct copy of the foregoing Notice dated April 19 <sup>th</sup> , 2005 regarding the property at 131 Linden Street Apt. B, was (MAILED CERTIFIED-RETURN RECEIPT REQUESTED) to: |  |  |
| Beverly S. Mitrisin, Substitute Trustee<br>for CitiCorp Mortgage, Inc.<br>ATTN: Stephen C. Porter<br>C/O Barrett Burke Wilson<br>Castle Daffin & Frappier, L. L. P.  |  |  |
| 15000 Surveyor Blvd., Suite 100  |  |  |
| Addison, Texas 75001   | n na an   |  |
|  | Date:<br>Time:   |  |
|  |  |  |
|  | Inspector  |  |

| I certify that a true and correct copy of the foregoi<br>property at 131 Linden Street Apt. B, was (MAILE<br>REQUESTED) to:   | ng Notice dated April 19 <sup>th</sup> , 2005 regarding the<br>D CERTIFIED-RETURN RECEIPT |
|---|---|
| Citicorp Mortgage, Inc.<br>ATTN: M. S. 321<br>15851 Clayton Rd.<br>Ballwin, MO 63011  |   |
|   | Date:<br>Time:  |
|   | Inspector   |
| I certify that a true and correct copy of the foregoin<br>property at 131 Linden Street Apt. B, was (MAILED<br>REQUESTED) to: | ng Notice dated April 19 <sup>th</sup> , 2005 regarding the DOCERTIFIED-RETURN RECEIPT    |
| Lidia Loera Martinez AKA Lindia Loera Chavez<br>and Frank Martinez<br>3024 Morehead Ave.<br>El Paso, Texas 79930              |   |
|   | Date: Time:   |
|   | Inspector   |
| I certify that a true and correct copy of the foregoin<br>property at 131 Linden Street Apt. B, was (MAILED<br>REQUESTED) to: | g Notice dated April 19 <sup>th</sup> , 2005 regarding the CERTIFIED-RETURN RECEIPT       |
| Charles M. Jackson, Jr., Trustee<br>10370 Richmond Suite 300<br>Houston, Texas 77042  |   |
|   | Date:<br>Time:  |
|   | Inspector   |
| I certify that a true and correct copy of the foregoing property at 131 Linden Street Apt. B, was (MAILED REQUESTED) to:      | g Notice dated April 19 <sup>th</sup> , 2005 regarding the CERTIFIED-RETURN RECEIPT       |
| North American Mortgage Co.<br>3883 Airway Dr.<br>Santa Rosa, CA 95403  |   |
| - · · · · · · · · · · · · · · · · · · ·   | Date: Time:   |
|   |   |

Inspector

| I certify that a true and correct copy of the forego property at 131 Linden Street Apt. B, was (HAND                              | ing Notice dated April 19 <sup>th</sup> , 2005 regarding the -DELIVERED) to:           |
|---|--|
| City of El Paso<br>C/O City Clerk<br>#2 Civic Center Plaza<br>El Paso, TX 79901   |  |
|   | Data   |
|   | Date:  |
|   | Time:  |
|   |  |
|   |  |
|   | Inspector  |
|   |  |
| I certify that a true and correct copy of the foregoi<br>property at 131 Linden Street Apt. B, was (MAILE<br>REQUESTED) to:       | ng Notice dated April 19 <sup>th</sup> , 2005 regarding the D CERTIFIED-RETURN RECEIPT |
| Governor of the Ysleta Del Sur Pueblo Indian Trib<br>AKA Tigua Indian Community<br>119 S. Old Pueblo Road<br>El Paso, Texas 79907 | e  |
|   | Date:  |
|   |  |
|   | Time:  |
|   |  |
|   |  |
|   | Inspector  |
|   |  |
| I certify that a true and correct copy of the foregoir property at 131 Linden Street Apt. B, was (MAILEI REQUESTED) to:           | ng Notice dated April 19 <sup>th</sup> , 2005 regarding the D CERTIFIED-RETURN RECEIPT |
| El Paso Central Appraisal District<br>5801 Trowbridge Ave.<br>El Paso, Texas 79925  |  |
|   | Date:  |
|   | Time:  |
|   | IIIIV.   |
|   |  |
|   | Inspector  |
| certify that a true and correct copy of the foregoin  | ng Notice was POSTED at  |

Date:\_\_\_ Time:\_\_\_

Inspector



## **UNSAFE STRUCTURES REPORT**

## **BUILDING PERMITS AND INSPECTIONS**

DATE OF EXAMINATION: April 20, 2005

**REP. DISTRICT: 3** 

ADDRESS: 131 Linden St.

ZONED: R-5

**LEGAL DESCRIPTION:** Lots: 13 and 14 and the North 20 feet of Lot 12, Block 1, TOBINS SECOND ADDITION, an Addition to the City of El Paso, El Paso County, Texas, according to the Map thereof on File in Book 16, Page 58, Plat Records of El Paso County, Texas

OWNER: Maria Lourdes Corral and Carlos J. Corral ADDRESS: 131 Linden St., El Paso, Texas 79905

BUILDING USE: Single-family dwelling

TYPE OF CONSTRUCTION: V

FOOTINGS: Unable to determine.

**CONDITION:** Unable to determine condition due to subterranean placement. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: N/A CONDITION:

FLOOR STRUCTURE: Slab on grade

CONDITION: Unable to determine condition. A structural engineer should be hired to evaluate

EXTERIOR WALLS: Masonry with stucco: Wood frame with wood siding.

**HEIGHT**: +/- 10' - 0"

THICKNESS: +/- 6"-12"

**CONDITION:** Bad, a structural engineer or licensed and bonded contractor should be hired to determine the damage and make repairs.

INTERIOR WALLS & CEILINGS: Wood frame, sheetrock and plaster.

CONDITION: Bad, a licensed and bonded contractor should be hired to make repairs.

ROOF STRUCTURE: Wood frame with build-up roofing.

CONDITION: Bad, a licensed and bonded contractor should be hire to determine any damage and make repairs.

DOORS, WINDOWS, ETC.: Wood frame

CONDITION: Some of the doors need to be replaced, and most of the windows are inoperable

MEANS OF EGRESS: Does not meet code.

**PLUMBING:** Bad. Will require a licensed plumbing contractor to verify condition and make repairs to meet code.

**ELECTRICAL:** Bad. Will require a licensed electrical contractor to verify condition and make repairs to meet code.

**MECHANICAL:** Bad. Will require a licensed mechanical contractor to verify condition and make repairs to meet code.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED:  $\,0\,$ 

WARNING POSTED: No

BARRICADED: No

POLICE AID REQD.:

**REMARKS:** This structure is a small apartment at the rear of the property. We recommend that a structural engineer be hired to make recommendation on the repairs of the structure, if the structure is to be rehabilitated, the electrical, plumbing and mechanical systems need to be brought up to current code. If the structure is not rehabilitated, we recommend that the structure be demolished and the property cleaned of all weeds, trash and debris.

Leo CassoLopez

**Building Inspector**